Packing Instruction | 1950AFE-R

PSN: UN1950, Aerosols, flammable, 2.1

Q1: Is each container > 1 L (61.0 cubic in.) capacity? IF YES, Use this packing instruction (PI). IF NO GO TO Q2

Q2: Is aerosol can charged to > 180 psig (1241.1 kPa) at 54.4°C (130°F)? IF YES, Use this PI, IF NO GO TO Q3

Q3: Is total weight (ALL contents + packaging) GREATER than (>) 66 lbs? IF YES, USE THIS INSTRUCTION.

IF YOU ANSWERED 'NO' TO Q1, Q2, AND Q3, USE PACKING INSTRUCTION 1950AFE-LQ TO PACK/SHIP PRODUCT

MODE OF TRANSPORT PROHIBITIONS: Ground shipping: ALLOWED | NO AIR OR VESSEL SHIPPING IS PERMITTED W/O WRITTEN AUTHORIZATION FROM LIIHAZMAT@LENNOXINTL.COM. IF WRITTEN AUTHORIZATION IS GIVEN, LIMITS ARE: Passenger aircraft/ rail: ALLOWED 165 lb (75 kg) limit Cargo aircraft: ALLOWED 331 lb (150 kg) limit Vessel: ALLOWED, Stowage Category A, 25, 87, 126

MATERIALS OF TRADE EXCEPTION - MAY BE SOLD BY LENNOX STORES TO TRADESMEN IN QUANTITIES NOT TO EXCEED A TOTAL OF 220 POUNDS (100 KILOGRAMS) OF PRODUCT UNLESS tradesmen shows proof of commercial drivers license (CDL) with hazardous materials /dangerous goods endorsement. If tradesman has endorsed CDL, sales volume limits do not apply.

## **CONTAINER & PACKAGING REQUIREMENTS**

ENN

RNATIONA

1

5

6

7

Use strong outer packaging appropriate for weight of contents (i.e. box must be rated for the maximum weight being placed in the box). If you cannot tell the weight rating of the box, please ask your supervisor and/or contact Lennox Environmental at liihazmat@lennoxintl.com or +1-972-497-7532.



ENNOX

Hornet

- Protect valves from leaking or damage by wrapping, using a cap, or other protective devices. If for any reason, wrapping, caps and protective devices are not available or practical, exemptions may apply. Contact LIIHazmat@lennoxintl.com for a waiver.
- Add separation materials to prevent damage to containers AND hold upright.
- Cardboard packing box must have a **PREPRINTED** UN symbol on it, and a rating of 4GV/X5/S, 4GV/X7/S, or 4G/Y24.2/S. IF A BOX IS REQUIRED to ship this product. If you do not have a U/N certified box contact your supervisor, you may not use a non-U/N certified box to ship this product.
- Box must be labeled with the Class 2 Flammable Gas Label on two opposite sides of box. NEVER PUT LABELS ON TOP OR BOTTOM OF BOX.
- Place the Consigner (Shipper/From) / Consignee (Receiver/To) on box with weather resistant marking.
- No Orientation Arrow is required for this UN number.


EXPLOSIVES

1,1

1.2

- Box must be marked with "UN1950" and "Aerosols, flammable, (each not exceeding 1 L capacity)" within 6 inches of labels in (5)
- If you are putting an inner package/box holding this product inside an outer box or on a pallet (i.e. using an 'overpack'). inner boxes MUST MEET THIS PACKING INSTRUCTION. AND, outer box or pallet shrinkwrap MUST BE MARKED and LABELED with every marking/label used on the inner boxes if not visible through the overpack. Outer box must have the OVERPACK marking.

An 'overpack' is a container (box, shrink-wrapped pallet, etc.) used to consolidate individual containers in an easier to ship form.



© 2022 Thrival Company

FOR QUESTIONS OR WAIVERS PLEASE CONTACT LIIHAZMAT@LENNOXINTL.COM



DO NOT SHIP UN1950AF IN THE SAME VEHICLE WITH THESE CLASSES DO NOT SHIP UN1950AF WITHOUT SEPARATION IN THE VEHICLE WITH THESE CLASSES





## Packing Instruction | 1950AFE-LQ

PSN: UN1950, Aerosols, flammable, 2.1, Ltd Qty

Q1: Is each container 1 L (61.0 cubic inches) capacity or less? IF YES, GO TO Q2, IF NO, USE PI-1950AFE-R

Q2: Is the aerosol can charged to 180 psig (1241.1 kPa) or less at 54.4°C (130°F)? IF YES, GO TO Q3, IF NO, USE PI-1950AFE-R

Q3: Is total weight (ALL contents + packaging) LESS than (<) 66 lbs? IF YES, USE THIS INSTRUCTION.

IF YOU ANSWERED 'NO' TO Q1, Q2, AND/OR Q3 USE PACKING INSTRUCTION 1950AFE-R TO PACK/SHIP PRODUCT

**MODE OF TRANSPORT PROHIBITIONS:** Ground shipping: ALLOWED | Passenger aircraft/rail: ALLOWED 165 lb(75 kg) limit | Cargo aircraft: ALLOWED 331 lb (150 kg) limit | Vessel: ALLOWED, Stowage Category A, 25, 87, 126

MATERIALS OF TRADE EXCEPTION - MAY BE SOLD BY LENNOX STORES TO TRADESMEN IN QUANTITIES NOT TO EXCEED A **TOTAL OF 220 POUNDS (100 KILOGRAMS) OF PRODUCT** UNLESS tradesmen shows proof of commercial drivers license (CDL) with hazardous materials /dangerous goods endorsement. If tradesman has endorsed CDL, sales volume limits do not apply.

## **CONTAINER & PACKAGING REQUIREMENTS**

1

LENNO

Use strong outer packaging appropriate for weight of contents (i.e. box must be rated for the maximum weight being placed in the box). If you cannot tell the weight rating of the box, please ask your supervisor and/or contact Lennox Environmental atliihazmat@lennoxintl.com or +1-972-497-7532.

Protect valves from leaking or damage by wrapping, using a cap, or other protective devices. If for any reason, wrapping, caps and protective devices are not available or practical, exemptions may apply. Contact LIIHazmat@lennoxintl.com for a waiver.

Add separation materials to prevent damage to containers AND hold upright.

Box must be marked with the Limited Quantity (LQ) markingon one side of box. Place the Consigner (Shipper/From) / Consignee (Receiver/To) on box with weather resistant marking.

No Orientation Arrow is required for gas cylinders.

If you are putting an inner package/box holding this product inside another box or on a pallet (i.e. using an 'overpack'), inner boxes MUST MEET THIS PACKING INSTRUCTION. AND, outer container or shrink wrap MUST BE MARKED and LABELED with every marking/label used on the inner boxes if not visible through the overpack. Outer box must have the OVERPACK marking.

An 'overpack' is a container (box, shrink-wrapped pallet, etc.) used to consolidate individual containers in an easier to ship form.

Weigh the completed package once all items have been added. Verify max gross weight of the package DOES NOT EXCEED 66 lbs (30 kg). If weight exceeds 66 pounds you must use PI-1950AFE-R for fully regulated hazardous materials packing instructions instead.

WARNING- If liihazmat@lennoxintl.com approves IN WRITING shipping by air or rail, you must add this label to two OPPOSITE sides of box(in addition to the LQ label) and not exceed the quantity limits under MODE OF TRANSPORT **PROHIBITIONS** listed above. IATA shipping papers are required for AIR SHIPPING.

SHIPPING PAPER CHECK IS REQUIRED Before providing shipping papers to a carrier, you must verify the product description on the shipping paper (bill of landing) is correct. If your package weighs 66 pounds (lbs) or less, you must add ", Ltd Qty" to the shipping paper using a pen after the description located in the SEE !!WARNING!! IMAGE. PACKAGE WEIGHT: By legal definition includes all contents including hazardous materials in one container or on a pallet yielding a TOTAL weight of shipment (not just individual hazardous material weight).

<u>AV</u>

1.3

EXPLOSIVES

1,1

EXPLOSIVES

1.2


FOR QUESTIONS OR WAIVERS PLEASE CONTACT LIIHAZMAT@LENNOXINTL.COM



8


DO NOT SHIP UN1950AF IN THE SAME VEHICLE WITH THESE CLASSES DO NOT SHIP UN1950AF WITHOUT SEPARATION IN THE VEHICLE WITH THESE CLASSES







## **!! SHIPPING PAPER WARNING !!** ADD ", LTD QTY" ON ANY SHIPMENT 66 LBS OR LESS



RADIOACTIVE

DISTRIBUTION THEREOF.

SUPPLIES USED IN THE MANUFACTURE, SALE, AND

1.5 BLASTING AGENTS EXPLOSIVES

1.4 4 TOXIC POISON

